

Dash Bezel Kit Contents

XK-120 OTS Early, to 661025 (RHD) and 672942 (LHD) Kit 16-0400

Part #	Quantity	Location(s)
C4625	One	“IGN” warning light with lens
C5465	One	Ignition switch (Lucas 304801); Listed as C2760 in parts book
C2763	One	Road lights switch (same as C4628)
C2769	Two	Oil pressure switch, Screen washer
C4631	One	Cigar lighter

XK-120 FHC to 669002 (RHD) and 680109 (LHD) Kit 16-0407

C4625	One	“IGN” warning light with lens
C4626	One	“TRF” warning light with lens
C5465	One	Ignition switch 304801; Listed as C2760 in parts book
C2763	One	Road lights switch (same as C4628)
C2769	Two	Oil pressure switch, Screen washer
C4631	One	Cigar lighter

**XK-120 FHC from 669003 (RHD) and 680110 (LHD);
OTS from 661026 (RHD) and 672950 (LHD) Kit 16-0401**

C4625	One	“IGN” warning light with lens
C4626	One	“TRF” warning light with lens
C5465	One	Ignition warning light (might be incorrect; actually ignition switch?)
C2763	One	Road lights switch (same as C4628)
C2769	Two	Screen wiper switch, Screen washer
C4630	Three	Starter, heater motor, panel lights
C4631	One	Cigar lighter

XK-120 DHC, ALL (Same as above) Kit 16-0401

C4625	One	“IGN” warning light with lens
C4626	One	“TRF” warning light with lens
C2763	One	Road lights switch (same as C4628)
C5465	One	Ignition switch
C2769	Two	Screen wiper, Screen washer
C4630	Three	Starter, heater motor and panel lights
C4631	One	Cigar lighter.

XK-140 OTS, ALL Kit 16-0408

C4625	One	“IGN” warning light with lens
C4626	One	“TRF” warning light with lens
C2763	One	Road lights switch (same as C4628)
C5465	One	Ignition switch
C2769	Two	Screen wiper switch, Screen washer
C4630	Three	Heater, panel and starter
C4631	One	Cigar Lighter

XK-140 DHC/FHC, ALL Kit 16-0402

C4625	One	“IGN” warning light with lens
C4626	One	“TRF” warning light with lens
C2763	One	Road lights switch (same as C4628)
C5465	One	Ignition switch
C2769	Three	Windscreen wiper switch, interior lights switch, Screen washer
C4630	Three	Heater, panel and starter switches
C4631	One	Cigar Lighter

XK-150 OTS/DHC/FHC, ALL**Kit 16-0403**

C2763	One	Road lights switch (same as C4628)
C4630	Four	Starter, panel, interior and heater switches
C5465	One	Ignition switch
C4631	One	Cigar lighter
C2769	Two	Screen Wiper, Screen Washer

MK VII, ALL**Kit 16-0404**

C4625	One	“IGN” warning light with lens
C4626	One	“TRF” warning light with lens
C4629	One	Ignition switch
C4630	One	Starter switch
C2763	One	Road lights switch (same as C4628)
C2769	Seven	Petrol change over, screen wiper, screen washer, panel lights/interior lights, map light, heater motor, heater tap
C4631	One	Cigar lighter.

MK VIII, ALL**Kit 16-0405**

C4625	One	“IGN” warning light with lens
C4626	One	“TRF” warning light with lens
C4629	One	Ignition switch (not listed in factory book but put in kit anyway)
C4630	One	Starter
C2763	One	Road lights switch (same as C4628)
C2769	Seven	Petrol changeover, screen wiper, screen washer, panel lights/interior lights, map light, heater motor and heater tap
C4631	One	Cigar lighter

MK IX, ALL**Kit 16-0406**

C4625	One	“IGN” warning light with lens
C4626	One	“TRF” warning light with lens
C4629	One	Ignition switch
C4630	One	Starter switch
C2763	One	Road lights switch (same as C4628)
C2769	Seven	Petrol changeover, screen wiper, screen washer, panel lights/interior lights, map light, heater motor, heater tap
C4631	One	Cigar lighter

MK I, ALL**Kit 16-0410**

C2763	One	Road Lights Switch
C4630	Three	Starter, Panel Lights, Heater Fan switches
C2769	Two	Windscreen Wiper, Windscreen Washer Valve
C4631	One	Cigar Lighter
C5465	One	Ignition Switch

Notes:

- For XK-120 Jaguar lists C2642 /Lucas 304853 for the IGN warning light bezel, but competition has sold same for all applications. How C2642 differs from **C4625** is unknown.
- Early 120 also does not have a “screen wiper” bezel. Could be that entire switch was supplied by Trico and has integral bezel?
- Early 120 lists C2760 as bezel for ignition switch (the one with the key). But, ignition switch is the same as cars that use C5465 bezel. In looking at cars in the shop, the early switch seems to protrude more, so perhaps the diameter of the bezel is the same but the length differs. Perhaps the thickness of the dash is different?